JC-1000 Automatic Winch and JCK-1 Winch Controller



Summary

JC-1000 Automatic Winch and JCK-1 Winch Controller are specially designed for borehole measurement in the field. It is used for lifting up and lowering down the probe. It has functions of automatic/manual, constant speed control, point measuring/continuously measuring, automatic depth correction, depth mutation alert. It can meet requirements of standard DZ/T 0196.8-1997 in the geological industry of the People's Republic of China. It is suitable for the boreholes in geology, metallurgy, coal field, oil field and engineering. It has special superiority in measuring deep holes.

I. Main technical features

- 1. Functions: Automatic/manual, constant speed control, point measuring/continuously measuring automatic depth correction.
- 2. High automation. The constant speed control can meet Class A in standard DZ/T 0196.8-1997.
- 3. Automatically break after an outage. Automatic stop protection when depth mutation occurs.
- 4. It has automatic brake function when using hand-cranking. Humanized.
- 5. LCD display. It shows information in real time.

II. Main technical specifications

- 1.JC-1000 Automatic Winch
- (1) Speed range: $(0 \sim 30)$ m/min
- (2) Depth range: $(0 \sim 1000)$ m
- (3) Control mode: JCK-1 Winch Controller
- (4) Working temperature : $(-10\sim70)$ °C
- (5) Power supply: AC (220±10%) V, 50Hz
- (6) Motor power: 1100W
- (7) Net weight: 110Kg (cable is not included)
- (8) Dimension: 700 mm×550 mm×700 mm
- 2. JCK-1 Winch Controller
- (1) Speed range: $(0\sim30)$ m/min. Automatic or manual.
- (2) Constant speed range : $(0.5\sim20)$ m/min. Bias is $\pm5\%$
- (3) Depth range: $(0 \sim 9999.99)$ m, bias $\leq \pm 0.4\%$
- (4) Control mode: Automatic, manual and verification
- (5) Control direction: Up and down.
- (6) Measuring mode: Point or continuous.
- (7) Signal: RS232 or pulse signal.
- (8) Working temperature : $(-10\sim55)$ °C
- (9) Power supply: AC220V±10%, 50Hz